

**From:** Johnston, Chris  
**To:** [Walsh, Linda;](#)  
**Subject:** RE: Culmore controller  
**Date:** 27 November 2015 18:35:00

---

Linda thanks and your suggestion seems spot on.  
Do you know what is left to do? Is the flow meter installed or the plc cabinet fixed in?

I reckon with the mad rush before 11<sup>th</sup> nov to beat the rhi change, boilers were being installed with the bare minimum to allow registration. Now all the work needs finishing properly ....

Talk soon  
Regards  
chris

Chris Johnston  
Tel:- 02892681540  
email:- [chris.johnston@afbini.gov.uk](mailto:chris.johnston@afbini.gov.uk)

---

**From:** Walsh, Linda  
**Sent:** 27 November 2015 10:48  
**To:** Johnston, Chris  
**Subject:** Culmore controller

Hi Chris,

Update ref Culmore controller.

Chris was up at Culmore – he fixed some damaged pipework and took samples. I had asked him to see Richard again about finishing off installation.

Remember I said they were busy before – well now Richard has said they are really busy. So the plan is to wait until spring time. If connected now they would have to prime it to see if running (all of this takes time)and then all pipework would have to be drained for wintertime for frost protection. So we fell it is best to wait, get it sorted and hopefully start irrigation again then. Just seems like the best plan at this time of year.

Hopefully OK with you.

Regards  
Linda